

NextEra Energy Transmission New York, Inc.

(NEETNY)

Empire State Line

Case 18-T-0499

Appendix K

Drainage Line Repair Plan

June 2020



NextEra Energy Transmission New York, Inc. (NEETNY) will minimize the potential for damaging drain tile by installing equipment matting in all areas where construction equipment will pass through agricultural fields. NEETNY's Agricultural Inspector (AI) will conduct a visual inspection immediately after equipment matting is removed from each field to check for evidence of drain tile damage. NEETNY will also provide all farm owners/operators with a telephone number to facilitate direct contact with the AI through the construction, restoration, and remediation phases of the Project.

In agricultural areas where construction activities result in damage to drain tile, as observed through visual inspection and/or communication with the farm owner/operator, NEETNY will repair the drain tile in accordance with the Natural Resources Conservation Service Practice Standards for subsurface drainage tiles and following Code 606 standards. All new plastic drain tubing will meet or exceed the American Association of State Highway and Transportation M252 specifications.

A schematic of the drain tile repair specifications is provided below.

